

GENERAL PRODUCT



SLIX™ RIPT

Inhibited Heavy-Duty Cleaner/Degreaser

FEATURES/BENEFITS

Phosphate free

Biodegradable

Free of petroleum solvents

Cleans heaviest deposits of grease and oil

No flash point

No odor

Inhibited against flash rust

Safer to user

Saves time with difficult cleaning

Pink liquid for easy visibility in totes

Restores appearance of floors and equipment

SlIx RIPT is available in 55 gallon drums and totes. Inquire about availability in other packages.
7899a.bul.wpd (Mar04)

Description

SlIx RIPT is a state of the art product, colored pink for easy visibility in totes, that is specifically designed for multiple tasks. *SlIx RIPT* will cut through the toughest petroleum-based soils, such as crude, bunker C and rolling oils and thick gear box lubes. In particular, cement floors and pump pads can be easily cleaned and whitened to a pleasing appearance. *SlIx RIPT* can also be used for the heaviest soils in locker rooms, machinery, transportation equipment and oil storage equipment. *SlIx RIPT* combines the highest quality detergents with special wetting agents to form a fast-acting cleaner that has hundreds of uses.

Directions for Use

For Normal Cleaning Applications:

Heavily soiled floors: Apply undiluted, brush with stiff bristle brush, rinse.

General floors: Mix 1:10 to 1:20 with water, mop or brush, rinse. Or use at 1:30 to 1:40 in automatic floor scrubbers.

Machinery: Mix 1:10 to 1:30, spray on, brush if necessary, rinse.

Steam cleaning: Mix 1:10 to 1:40. Pre-wet surface.

Transportation equipment: Mix 1:10. Wash from bottom up.

High Pressure Washing: Mix 1:10 to 1:40.

Fuel Vapor Purging Procedure:

1. Drain the tank of all gasoline. Tilt, shake, or invert as necessary to ensure the tank is empty.
2. Pull the sending unit to provide a second access for venting.
3. Blow air through the tank to aid in drainage of excess gasoline. Tilt or invert as necessary to let gasoline drain through openings. After drainage slows to a trickle (about 1 drop per minute), continue air purging for 30 minutes or longer.
4. Add a premixed solution containing 2% *SlIx RIPT* in water. Fill the tank to approximately 90% full with the *SlIx RIPT* solution.
5. Set the tank aside and blow air through the *SlIx RIPT* solution. Reposition the air stream periodically as necessary to ensure all areas of the inner tank are in contact with the *SlIx RIPT* solution in an agitating fashion. (Extra care taken during steps 1 thru 3 will reduce the purging time necessary here.)
6. Test the tank with an explosive vapor monitor until no flammable vapors are detected.
7. Drain the tank and rinse with hose until free of *SlIx RIPT* solution.

Caution: Always check with local authorities before disposing of solution.

IMPORTANT: Before using *SlIx RIPT*, always be sure to read and follow warnings and directions for use appearing on the product container label and MSDS.

Penetone Corporation • 700 Gotham Parkway • Carlstadt, NJ 07072 • (800) 631-1652
West Penetone, Inc. • 10900 Secant St. • Ville d'Anjou, QC H1J 1S5 • (514) 355-4660



YOUR CLEANING SOLUTIONS RESOURCE.